

US EPA ARCHIVE DOCUMENT

1. Incident Name	2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill	12/18/2012	2115		
4. Unit Name/Designators	5. Unit Leader		6. Operational Period :	
Containment Branch Recovery Team 6 (CBR-6)	Name:	Dan Capone START/US EPA	From:	12/17/2012 0700
	Position:	Operations Section Chief	To:	12/17/2012 1800
7. Personnel Roster Assigned				
<u>Name</u>	ICS Position			
Dan Capone	Operations Section Chief			
Rex Johnson	Containment Branch Director			
Sean Kane	Field Team Lead/CBR-3			
8. Activity Log				
Activity Area	(MP 37.75 LDB Morrow Lake Delta, Islands A & B)	LAT	LAT	
		Various	Various	
		(DD.MMMM)	(DD.MMMM)	
<u>OIL OBSERVED</u>	EXTENT OF OIL IMPACTED AREA			
	DENSITY OF OIL /SHEEN			
Total Collection Points				
Total Boom Deployed				
Activity	<u>Weston/START CBR 3 Team Activity:</u> General oversight documentation (photo and written) of Enbridge bathymetric survey team # 1 led by Luke Hodges (Stantec). Enbridge field team conducted survey measurements within the operational area of MP 37.75 LDB (Islands A & B) and completed transects; MP 37.75L (26 survey points), MP37.75M (39 survey points), MP37.75N (36 survey points).			
Health and Safety Issues	None			
Comments	Cylindrical sampling device's (CSD's) associated within the operational area were temporarily removed prior to intrusive survey activities and replaced accordingly (i.e., orientation as related to perspective banks) after post survey activities.			

	Detailed field notes will be found in CBR-6 logbook.
--	--